

CASIO COMPUTER CO., LTD.

6-2, Hon-machi 1-chome

Shibuya-ku, Tokyo 151-8543, Japan

Telephone: +81-3-5334-4771

Facsimile: +81-3-5334-4656

URL: world.casio.com



PA TECHNICAL BULLETIN

Technical Bulletin No. : TB-PA - 2002013

Date: July 11th, 2002

MODEL: DT-700/DT-710/DT-750/DT-900 Series

SUBJECT : Release of Revised Communication Driver Software

Dear CASIO Distributors,

We hereby announce that the "**Communication Driver Software (for MULTIDROP) Version 1.07**" for DT-700/DT-710/DT-750 series and "the **Communication Driver Software (for MULTIDROP) Version 1.01**" for DT-900 series, both run under Windows95/98/ME/NT/2000 are available now.

For detail about the files and the release procedures, refer to the following pages.

A handwritten signature in black ink, appearing to read "Yoshimura", is positioned above a horizontal line.

Tsutomu YOSHIMURA

General Manager

Overseas Marketing and Sales Department

System Products Division

1. Revision

The communication driver software, **version 1.07** for DT-700, DT-710 and DT-750 , and **version 1.01** for DT-900 have been revised due to the following problem.

Problem solved;

Communication between one of the models mentioned and a PC cannot be continued if “Parity” is set enabled at the communication parameter setting on the PC. This is apparent when the software runs under Windows NT 4.0.

In addition to the countermeasure above, a new feature has been implemented in **version 1.01** for DT-900.

New feature;

Communication at baud rate, 38.4Kbps, 57.6Kbps or 115.2Kbps, is possible with the console version "UDWIN.EXE version 2.00". Its DLL file is "HOSTCOM.DLL version 2.01".

Notes:

- In case you use MULTIDROP ver. 1.02, replace manually the previous "HOSTCM32.DLL" in the system directory of Windows with that of this version.
Or if you use “MULTIDROP ver. 2.00, replace manually the previous “HOSTCM32.DLL” in the same directory with that of the "MULTI32E.exe" program with that of this version.
- For detail of the console version, refer to the "DT-900 Series Upload/Download Utility Manual" by clicking <http://www.casio.co.jp/English/system/pa/PADealer/manual/manual/dt900/up-down.pdf>

2. Release of Files

The revised patch files can be fetched at CASIO WEB page. Click the following URLs to download. Or, if you wish to have the same files to be sent to you, we can provide you with either e-mail attachment files or floppy diskette at your choice.

- **Communication Driver Version 1.01 for DT-900**

URL: http://www.casio.co.jp/English/system/pa/PADealer/sup21_main.html

File Name	Version	Size	Date
DI_wnt101.zip	1.01	75,907 bytes	July 11, 2002
Included sub-files are;			
Hostcm32.dll	2.01	47,616 bytes	May 7, 2002
hostcom.dll	2.01	55,296 bytes	May 7, 2002
Udwin32.exe	2.00	36,864 bytes	May 7, 2002

- **Communication Driver Version 1.07 for DT-700/DT-710/DT-750**

URL: http://www.casio.co.jp/English/system/pa/PADealer/sup05_main.html

File Name	Version	Size	Date
DI_wnt107.zip	1.07	75,907 bytes	July 11, 2002
Included sub-files are;			
Hostcm32.ocx	1.00	24,576 bytes	July 10 1996
Hostcm32.dll	1.05	47,616 bytes	April 19 2002
hostcom.dll	1.05	55,296 bytes	April 19 2002
Udwin32.dll	1.02	36864 bytes	April 12 1999

3. Support

Support for the software product is provided by us (CASIO Tokyo) for all the geographic areas with exception of European countries (West). All European countries are supported by CASIO EU office in Germany. If you are situated in the area, please contact with CASIO EU for any support you may need.

Information in this bulletin is subject to change without a prior notice.

Contact at ;

CASIO Tokyo	Mr. H. Takahashi	tak13694@sumigw.su.casio.co.jp
-------------	------------------	--

CASIO EU	Mr. Arne Reinelt	Europeht@casio.de
----------	------------------	--

- End of the Bulletin -